


3204C Series REX Direct Surface Mounting Stencil

Use your own hardware.

The bottom of the enclosure has four pre-drilled holes for surface mounting.
Distance between the enclosure mounting holes: 42.0mm x 163.0mm



1. Mark the center point of each of the four holes on your mounting surface either by directly measuring or using this stencil.
2. Hardware recommendation: M3 locking washers and M3 screws (4 of each per extender) noting screw length will depend upon thickness of mounting surface.
3. Drill through each of the four hole markings on the mounting surface using a 3.97mm (5/32") drill bit.
4. Align the bottom enclosure holes to the newly drilled out holes on the mounting surface.
5. Place a locking washer on each of the four screws and using a screwdriver, fasten the extender into place.

NOTES: Do not exceed a screw depth of 10mm (0.4") into the unit or damage may occur.

To print this stencil to scale, either select the print dialogue box to "actual size" or set page scaling to "none".

#90-01968-A01

